Cumberland Packaging Ltd

HAZARD ANALYSIS STUDY REPORT

Date of assessment: 21 June 2021

Review date (1): Review date (2): Review date (3):

Approved By	Mr. J. Watson
Signature	
Position	Managing Director
Approval Date	
Issue number	Eight (8)

Terms of reference

The HARA study covers all products manufactured at the Cumberland Packaging Ltd site and has been conducted in accordance with the manufacture and supply of corrugated packaging products intended as a packaging medium for indirect food contact by the customer.

The aims and objectives of the organisation is to gain accreditation of the BRC Global Standard for Packaging and packaging materials <u>Issue 6.</u>

Scope

The study covers the flexographic printing, die-cutting, slotting, gluing and stitching, of corrugated fibre board to produce plain and printed multipoint glued cases, trays and inserts with cut or un-cut purchased polystyrene void fitments adhered with PVA glue to use as secondary packaging for food and consumer products.

The food and hygiene sensitive safety hazards considered by the study are microbiological, foreign objects and chemical contamination, as well as possible packaging defects critical to consumer safety.

All elements of the HARA study have been carried out by the following HARA Team;

1) Mr. M. Bennett Production Manager (Authorised HARA Team Leader)

Mr. J. Watson Managing Director
 Mr. I. Stubbles Compliance Officer
 Mr. C. Monaghan Production Director
 Mis. Jody Adams Senior account handier.

The HARA Team will review the HARA Study annually in accordance with the requirements of the company's management review meeting and or following significant changes to the process or product range supplied to the customer.

Product description and intended use

Cumberland Packaging Ltd manufacture and supply corrugated packaging products that are used by our customers to provide a secondary packaging medium to their products.

The products are supplied in flat form and are identified with the product details for trace ability purposes should the need arise. We ensure our suppliers provide appropriate and documented certification to demonstrate conformance to current legislation.

All of our raw materials are sourced from BRC certified Suppliers and all suppliers are currently also hold FSC Chain Of Custody Certification. We only use raw materials from our approved suppliers and never use recycled materials from our customers.


Cumberland Packaging Ltd classify our products as low/medium risk as they are not used in direct contact with food and other hygiene sensitive products. However the products may be utilised in higher risk category's by our packer fillers.

Any contamination of the product which could be transferred to the customers product or may pose a risk to end users is extremely important therefore that we identify all potential food safety hazards throughout our manufacturing process and implement appropriate control measures.

Process flow diagram

The process flow diagram details the process steps and prerequisites of the production process from specification and contract review to delivery of finished product to the customer.

Process controls ensure products meet customer requirements.



Process flow verification / change log

The HARA team has agreed the food safety hazards associated with each process step. The HARA study and the control and monitoring measure will be reviewed at least annually and or following a significant process change. All amendments are recorded on the following verification form.

Date	Amendment	Signature
21-06-2021	Scope of HARA updated and HARA updated as issue eight (8)	lan Stubbles

Pre-requisites food safety hazards

Foreign Objects And contaminants:

- Blades / Sharps / staples
- · Off-cuts and other product related waste
- Blood/Bodily fluids
- Taints & odours
- Glass, brittle plastic or ceramic
- · Compressed air
- Wood
- Soil
- Pests (rodents, mice, birds)
- Insects
- Jewellery and other personal items
- Hair
- Food stuffs
- Malicious contamination/ Food defence
- Food fraud
- Extraneous matter

Chemicals

- Oil
- Cleaning materials
- Grease
- Glue
- Solvents

Hazard analysis - risk to product safety and integrity

L = **Likelihood** of the Occurrence

 $\frac{\mathbf{S} = \mathbf{Severity of the Outcome}}{3 = \mathbf{High}}$

 $R = Risk Level (L \times S)$

3 = High

2 = Medium

1-3 = Low risk (establish control measures where appropriate)

1 = Low

2 = Medium

1 = Low

4-6 = Medium risk (establish control measures)

9 = Substantial risk to integrity (Critical Control Point)

Hazard Analysis

Hazaru Anary					lary	515			
Process Step	Hazard	Туре	L	s	R	ССР	Control Measures	Manual / Reference Document	
•	Glass and brittle plastics	F	1	3	3	NO	Minimise glass in the factory and audit. Ensure glass breakage action and investigation systems are in	Glass and brittle plastic control procedure Part 2, section 9. (procedure 5.7.2)	
Analysed in the table are the contamination	Blades/Sharps and Staples	F	1	3	3	NO	System for safe issue, return and disposal of blades. Ensure blade loss/damage action and investigation systems are in place. No staples/D,Pins in production.	Knives & Blade control procedure Part 2, section 10. (procedure 5.7.11)	
and allergen hazards that may	Pests	М	1	3	3	NO	Ensure effective and meaningful pest control systems are in place and maintained	Pest control surveillance records & action reports Part 1, section 19.	
be present throughout the manufacturing process.	Personnel/Mali cious attack	F/M/C	1	2	2	NO	Clearly communicate personal hygiene rules and ensure hygienic conditions are monitored by audits. Personnel are all vetted at induction stage and site security is controlled. Personnel are all trained and refreshed in Hygiene requirements.	Hygiene Code of Practice Part 1, section 14. (1.1 to 1.6 Inclusive) Risk assessment for security annually reviewed. Part 7, competence awareness and training policys.	
The hazards detailed are not process specific and are controlled	Dust, dirt and compressed air, Unintended migration	F/M/C	1	2	2	NO	Ensure all cleaning and maintenance requirements are specified and are carried out as scheduled.	Hygiene Code of Practice Part 1, section 16 & 17	
by essential factory wide	Wood splinters	F	1	1	1	NO	All wood (pallets/tops/work stations, etc) damage or defects to be reported to management.	Contamination control Part 1, section 9.	
procedures.	Hairs	F/M	1	1	1	NO	Hair to be covered as deemed appropriate by management at all times. (Safety & Hygiene)	Hygiene Code of Practice Part 1, section14, page 2, (1.4.b)	
	Blood & B.F.	М	1	1	1	NO	Ensure accidents are reported immediately and cuts are suitably protected	Hygiene Code of Practice Part 1, section 14, page 1 (1.2)	
	Foodstuffs Bacteria/ pathogens	F/M	1	1	1	NO	Restrict food and drink to designated areas outside of production	Hygiene Code of Practice Part 1, section 14, page 1, (1.6.1 & 1.6.2)	
	Jewellery and personal items	F	1	1	1	NO	Restrict wearing of jewellery and bringing of personal items into production areas	Hygiene Code of Practice Part 1, section 14, page 2 (1.5)	

CCP = Critical Control Point

F = Foreign Body hazard

M = Microbiological hazard

Hazard Analysis

					•			
Process Step	Hazard	Туре	L	S	R	ССР	Control Measures	Manual / Reference Document
Print approval,	Contamination caused by printing or deliberate fraud	F/M/C	1	1	1	NO	Ensure the approval process and ink selection procedure is followed. Particular attention to the approval process requesting permission to print the brand. Line clearance for excess packaging.	Contamination control Part 1, section 9. Control of artwork
Raw material / Product / source & receipt	Poor handling and hygiene controls at suppliers	F/M/C	1	1	1	NO	Only purchase raw material/product from approved suppliers/sub-contractors who can demonstrate the required level of hygiene controls. Auditing and approval status	Assessment of Suppliers & Sub-contractors Part 2, section 2. (procedure 3.5.1)
·	Contaminated deliveries / Malicious	F/M/C	1	1	1	NO	Ensure all deliveries of raw material are inspected for odour, damp, damage or contamination including deliberate contamination.	Contamination control Part 1, section 9. Control of non-conforming products Part 2, section 8. (procedure 5.6.1)
Process Step	Hazard	Туре	L	S	R	ССР	Control Measures	Manual / Reference Document
Storage of raw material	Inappropriate/poor handling and hygiene controls in Stores	F/M.	1	1	1	NO	Ensure that all raw materials remain in original packaging until issued to production. Ensure that the stores department cleaning schedule is applied and external doors are kept closed when not in use	Contamination control Part 1, section 9. Hygiene Code of Practice Part 1, section 16, (3.1.1 to 3.8.1 Inclusive) & Part 1, section 17, page 2. (4.4.8)
Process Step	Hazard	Туре	L	S	R	ССР	Control Measures	Manual / Reference Document
Unpacked for production	Contamination caused by poor handling and hygiene controls in Stores	F/M	1	1	1	NO	Ensure that all raw material is inspected for odour, damp or contamination when unpacking and is stored on clean pallets for issue to production Ensure that all personal hygiene rules are applied	Contamination control Part 1, section 9. Hygiene Code of Practice Part 1, section 14. (1.1 to 1.6.3 Inclusive)

CCP = Critical Control Point

F = Foreign Body hazard

M = Microbiological hazard

Hazard Analysis

Process Step	Hazard	Туре	L	S	R	ССР	Control Measures	Manual Reference Document
Raw material converted into the finished product	Product contamination in machine set-up caused by poor equipment controls	F/C	1	1	1	NO	Ensure setting tools and associated equipment are removed and placed in the designated and safe area on completion of machine set. Carry out visual checks on a regular basis.	Hygiene Code of Practice Part 1, section 18, page 2. (5.5.9 a & b)
	Contamination during board manufacture and conversion caused by poor hygiene and process inspection controls.	F/M/C	1	1	1	NO	Ensure physical and visual quality and hygiene inspections are carried out in accordance with documented criteria. Maintain GMP and hygiene culture at all times. Report defective equipment/product or incidents of contamination/poor quality and product safety concerns in every instance. Ensure cutting formes, printing dies etc are in sound condition at all times (prior to and after use)	Process control, inspection and test. Part 2, section 7. (procedure 5.2.1) Contamination control Part 1, section 9. Control of non-conforming products Part 2, section 8. (procedure 5.6.1)
	Contamination of finished product caused by packaging/wrapping	F/M/C	1	1	1	NO	Carry out visual inspections of product packaging/wrapping at clearly defined intervals	Process control, inspection and test. Part 2, section 7. (procedure 5.2.1)
Finished Product palletisation, Identification & preservervation	Contamination caused by poor palletisation and handling controls	F/M/C	1	1	1	NO	Ensure that the product is adequately protected from the environment and is free from contamination and strapping damage. Ensure that customer palletisation and protection specifications are adhered to at all times. Ensure the pallet/product label is attached	Process control, inspection and test. Part 2, section 7. (procedure 5.2.1) Finished product inspection and test procedure.

CCP = Critical Control Point

F = Foreign Body hazard

M = Microbiological hazard

Hazard Analysis

Process Step	Hazard	Туре	L	S	R	CCP	Control Measures	Manual Reference Document
Storage of finished product	Contamination caused by poor handling and hygiene controls in finished goods stores	F	1	1	1	NO	Ensure that all finished product remain in original and appropriate packaging until released for delivery. Ensure that the stores department cleaning schedule is applied and external doors are kept closed when not in use	Contamination control Part 1, section 9. Hygiene Code of Practice Part 1, section 16, (3.1.1 to 3.8.1 Inclusive) & Part 1, section 17, page 2. (4.4.8)
Process Step	Hazard	Туре	L	s	R	ССР	Control Measures	Manual Reference Document
Transportation of finished product	Generic contamination caused by poor handling and hygiene controls of delivery vehicle trailer.	F	1	1	1	NO	Ensure that the trailer is inspected for odour, damp or contamination prior to and after each delivery. Ensure that trailer curtains are free from damage prior to and after each delivery. Ensure that all personal hygiene rules are applied	Contamination control Part 1, section 9.
Process Step	Hazard	Туре	L	s	R	ССР	Control Measures	Manual Reference Document
Contractor/ Employee(inc temp workers). Servicing, Maintenance, and Repair.	Contamination caused by lack of controls with regard to due diligence and safety.	F/M/C	1	1	1	NO	Ensure that contractor duties are adhered to at all times. Supervise activities and apply strict control measures. Ensure that all personal hygiene and site rules are applied and adhered to.	Maintenance staff/Contractor duties Part 1, section 18, page 2. (5.5.8) Interviews and induction to all new employees and agency personnel. In accordance with good personnel practices Part 1, section 7
Process Step	Hazard	Туре	L	S	R	ССР	Control Measures	Manual Reference Document
Drivers/ Visitors. Conduct whilst on site	Lack of regard to due diligence and safety.	F/M/C	1	1	1	NO	Ensure that Drivers/Visitors are made aware of their responsibilities whilst on site. Supervise activities and apply strict control measures. Ensure that all personal hygiene and site rules are applied and adhered to.	Hygiene/safety information leaflet issued in every instance and reviewed with management Part 1, section 9, page 4

CCP = Critical Control Point

F = Foreign Body hazard

M = Microbiological hazard